

















Barstool Jack


ASSEMBLY INSTRUCTION

A  x1	B  x1	C  x1	D  x1	E  M8x30 x3	F  M6x16 x2	G  x4	H  x5
I  #5 x1	J  M6x20 x2	Spare Parts  M8x30 x1	Spare Parts  M6x16 x1	Spare Parts  M6x20 x2	Spare Parts  x1	Spare Parts  x1	


STEP 1



STEP 23



STEP 3



STEP 4

