




<p><b>A</b></p> 	<p><b>B</b></p> 	<p><b>C</b></p> 	<p><b>D</b></p> 	<p><b>E</b></p>  <p>ø18*1.5mm</p> <p>X7</p>	<p><b>F</b></p>  <p>M6*20mm</p> <p>X2</p>	<p><b>G</b></p>  <p>M6*25mm</p> <p>X5</p>	<p><b>H</b></p>  <p>M6*35mm</p> <p>X4</p>	<p><b>I</b></p>  <p>M4</p> <p>X1</p>
--	---	---	---	--	--	--	--	---

STEP1



<p>Extra Parts</p>  <p>ø18*1.5mm</p> <p>X1</p>	<p>Extra Parts</p>  <p>M6*20mm</p> <p>X1</p>	<p>Extra Parts</p>  <p>M6*25mm</p> <p>X1</p>	<p>Extra Parts</p>  <p>M6*35mm</p> <p>X1</p>	<p>Extra Parts</p>  <p>X1</p>
---	---	---	---	--

STEP2

